

**SPX****POWER TEAM®**

SPX Corporation  
5885 11th Street  
Rockford, IL 61109-3699 USA

Tech. Services: (800) 477-8326  
Fax: (800) 765-8326  
Order Entry: (800) 541-1418  
Fax: (800) 288-7031


Internet Address:  
<http://www.powerteam.com>

Form No. 100731

Parts List for:

1600

**MODEL B**  
**BEAD BREAKER**  
Max. Capacity: 11.2 Ton at 10,000 PSI




| Item No. | Part No. | Req'd | Description                                  |
|----------|----------|-------|--|
| 1        | 36958    | 1     | Hook   |
| 2        | 22469    | 1     | Soc. Hd. Shoulder Screw (5/8-11 X 2-1/4 Lg.) |
| 3        | 41086    | 1     | Clevis                                       |
| 4        | 4108     | 1     | Frame  |
| 5        | 206869   | 1     | Trade Name Decal                             |
| 6        | 34184    | 1     | Hex Hd. Screw                                |
| 7        | 28705FA  | 1     | Foot Assembly                                |

Note: Shaded areas reflect last revision(s) made to this form.

Sheet No. 1 of 2

SINGLE-ACTING, SPRING RETURN  
HYDRAULIC CYLINDER

Max. Capacity: 11.2 Tons at 10,000 PSI.




| Item<br>No. | Part<br>No. | No.<br>Req'd | Description   |
|-------------|-------------|--------------|---|
| 1           | 202179      | 1            | Thread Adapter (Torque to 100 ft./lb.)                          |
| 2           | 201365      | 1            | Retainer Nut (Torque to 40/50 in./lb.)                          |
| 3           | *20142      | 1            | Rod Wiper   |
| 4           | 10008       | 2            | Soc. Hd. Cap Screw (1/4-20 X 3/4 Lg.; Torque to 90/110 in. lb.) |
| 5           | *10442      | 2            | Copper Washer (3/8 X 1/4 X 1/32)                                |
| 6           | 36087       | 1            | Piston Rod  |
| 7           | 201433      | 1            | Retaining Ring  |
| 8           | 201363      | 1            | Piston Head   |
| 9           | *16067      | 1            | U-cup Piston Seal   |
| 10          | 201359      | 1            | Slip Retainer   |
| 11          | *16076      | 1            | Retaining Ring  |
| 12          | 201360      | 2            | Spring Retainer   |
| 13          | 201430      | 1            | Extension Spring (See detail below)                             |
| 14          | 42158       | 1            | Cylinder Body   |

## PARTS INCLUDED BUT NOT SHOWN

9796      1      Ram Half Coupler w/ Dust Cap

Part numbers marked with an asterisk (\*) are contained in Repair Kit No. 300116.

**SPRING & RETAINER ASSEMBLY**

Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. **Therefore: Use only genuine Power Team replacement parts!**

Additional questions can be directed to our Technical Services Department.

Note: Shaded areas reflect last revision(s) made to this form.

Sheet No. 2 of 2

Rev. 1 Date: 21 April 2003